



U.S. Department  
of Transportation  
**Federal Aviation  
Administration**



# SDR

Service Difficulty Reporting

## Summary

January 25, 1998 - January 31, 1998

GENERAL AVIATION, ZAC-327

*You can improve Air Safety by reporting the problem when you see it!*

---

### SECTION

- I Significant Occurrence Report
- II Domestic Service Difficulty Report
- III International Service Difficulty Report
- IV SDR Totals by District Office
- V Index By Aircraft Make and Model
- VI Joint Aircraft System/Component Code Table

ISSUE: 98-05



U.S. Department  
of Transportation  
**Federal Aviation  
Administration**

# **SDR SUMMARY**

General Aviation, ZAC-327



This summary includes domestic (United States) Service Difficulty Reports (SDRs) entered into the data base for aircraft weighing 12,500 lbs. and below. It also includes reports on aeronautical products (engines, propellers, and components), and all helicopters. A separate section for International SDRs for aircraft weighing 12,500 lbs. and under has also been included. Under a data exchange agreement, International SDRs are submitted to the FAA by the Civil Aviation Authority of other countries (currently, Canada - CAN, and Australia - AUS). All reports are sorted by aircraft make, model group (basic model), and Joint Aircraft System/Component (JASC) code. Within each aircraft model group, the specific model shown may vary, but similar types of reports will be grouped together and listed in ascending order by their JASC code. Each field contains all information submitted to the FAA. Some fields are not included in order to make the summary easier to read. Additional information may be obtained by referring to the "operator control number." Send your request to the Aviation Data Systems Branch, AFS-620 at the address or phone below.

The Regulatory Support Division (AFS-600) has established a "HomePage" on the Internet through which the same information is available. There is a large quantity of other information available through the AFS-600 HomePage such as the most current SDR system codes (i.e., Joint Aircraft System/Component Codes). The SDR Question and Answer Section of the Summary will also be transferred to the AFS-600 HomePage to simplify the process of preparing the SDR Summaries in the PDF format each week. There are "hot buttons" to take you to other locations and sites where FAA Flight Standards Service Information is available. The AFS-600 "HomePage" address is:

**<http://www.mmac.jccbi.gov/afs/afs600>**

**"The Service Difficulty Reports in this publication are derived from unverified information submitted by the aviation community without FAA verification for accuracy. The number of SDRs submitted is not an indication of the mechanical reliability or fitness of an airline or individual operator, and the information should not be used as such."**

Comments are welcomed and may be directed to:


*Federal Aviation Administration  
Aviation Data Systems Branch, AFS-620  
P.O. Box 25082  
Oklahoma City, OK 73125-5029  
Phone: (405) 954-4171, Fax: (405) 954-4748*

Your continued participation is essential and is an integral part of ensuring aviation safety. Thank you for supporting the Service Difficulty Program! If you have any questions regarding this special notice you can contact John Jackson at (405) 954-6486, or Jim Gillespie at (405) 954-1141, or Blake McDonald at (405) 954-0307 in the Aviation Systems Branch (AFS-620). Their E-mail addresses are:

**[john\\_e\\_jackson@mmacmail.jccbi.gov](mailto:john_e_jackson@mmacmail.jccbi.gov)**

**[james\\_gillespie@mmacmail.jccbi.gov](mailto:james_gillespie@mmacmail.jccbi.gov)**

**[blake\\_mcdonald@mmacmail.jccbi.gov](mailto:blake_mcdonald@mmacmail.jccbi.gov)**



# **SIGNIFICANT OCCURRENCE REPORT**





U.S. Department  
of Transportation  
**Federal Aviation  
Administration**

## **THE SIGNIFICANT OCCURRENCE REPORT**



The Significant Occurrence Report is a compilation all of the star bordered reports that appear in the General Aviation Service Difficulty Report (SDR) Summary, ZAC-327. The Significant Occurrence Report is used to highlight industry problem areas to field inspectors and the aviation public.

Limited analysis is performed by the Aviation Data Systems Branch, AFS-620 during the preparation of the "Significant Occurrence Report", which is generated each week and is included in the front of the Air Carrier SDR Summary. Significant Reports are hand selected by AFS-620's inspectors based on the individual merit of each report. The criteria for selection includes, but is not limited to, items that indicate high failure rates; items related to accidents or incidents; or design or maintenance failures which may affect the safe operation of the aircraft.

In some cases, this limited analysis of SDR data leads to the preparation of information bulletins which are routed to the appropriate product certification office for further investigation of the problem. The end result may be the issuance of an airworthiness directive (AD) by the Aircraft Certification Service (AIR) if warranted.

The Significant Occurrence Report (section I) of the weekly SDR Summary is not intended to be a summary of all significant events and should not be used as such. We recommend that you review further the applicable sections of the SDR summary that may be of interest.

# GENERAL AVIATION SIGNIFICANT OCCURRENCE REPORT

1/25/98 - 1/31/98    ISSUE: 98-05    ZAC-327

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
5312	222HX	BELL				BULKHEAD	CRACKED		1/14/98
RMXA	47533	222U				222031056103	BS 270		98ZZZX324
*****	FOUND 2 EACH CRACKS IN AFT MAIN ROOF BEAM AT LT NODAL BEAM SUPPORT. BS 270, WL 79.0, LBL 9.90.								
3310	403ER	CESSNA				DIMMER ASSY	MISWIRED	34	12/1/97
N3XR	17280245	172R				15703014	INST LIGHTS		98ZZZX359
*****	DURING A TRAINING FLIGHT, THE CREW SMELLED A BURNING SCENT. AFTER FOLLOWING THE EMERGENCY CHECKLIST, THEY WERE GOING TO LAND OFF-FIELD. THE SMELL DIMINISHED AND THEY PROCEEDED TO X-47. DURING THE FOLLOWING INSPECTION, A RESISTOR WAS FOUND BURNED IN HALF ON THE DIMMER ASSY. IT WAS DISCOVERED THE UNIT IS WIRED INCORRECTLY. IT APPEARS TO BE A FLEET PROBLEM. AFTER A CALL TO CESSNA, DISABLED THE DIMMERS IN THE ENTIRE FLEET. SB 97-33-01 APPLIES.								
5512	732XE	CESSNA				RIB	CRACKED	3197	1/7/98
	2061850	T210M			123260029		H STAB LT/RT		98ZZZX318
*****	DURING ANNUAL INSPECTION, A CLICKING NOISE WAS HEARD WHILE PRESSING THE LEADING EDGE OF THE HORIZONTAL STABILIZER AT THE RIBS. WITH FURTHER INSPECTION, SEVERAL RIBS FOUND CRACKED ON BOTH LT AND RT SIDES OF THE STABILIZER. ALSO, FOUND ON THIS ACFT, RIB PN 1232105-1 HAS BEEN BENT. THIS IS 3RD T210 THAT HAS BEEN FOUND WITH CRACKED LEADING EDGE RIBS AND ALSO FOUND SEVERAL TU206 ACFT WITH THIS SAME CONDITION. IT APPEARS THAT YEARS OF PUSHING ON STAB DURING GROUND HANDLING HAS HELPED TO CREATE THIS CONDITION. TT ON ALL ACFT IS APPROXIMATELY 3,000 HRS.								
3060	340MT	CESSNA				BREAKER	FAILED		12/15/97
	340A0741	340A				W31X2M1620	PROPELLER DEICE		98ZZZX349
*****	PROPELLER DE-ICE WAS SELECTED ON AIRCRAFT CLIMBING THROUGH SNOW FLURRIES. THE PROPELLER DE-ICE PIGTAIL WIRES AT PROPELLER HUB WERE SHORTED TO THE SPINNER. THIS CAUSED SMOKE IN THE COCKPIT. AIRCRAFT RETURNED AND MADE AN UNEVENTFUL LANDING. THE PROPELLER DE-ICE CIRCUIT BREAKER DID NOT TRIP TO THE OFF OR OPEN POSITION ALLOWING THE WIRING FROM THE CIRCUIT BREAKER TO THE DE-ICE GAUGE TO BURN IN TWO.								
5320	29MM	CESSNA				DOUBLER	CRACKED	7936	12/15/97
HBCA	402B0863	402B				52130452	NLG RT WELL SKIN		98ZZZX347
*****	DURING A 100-HOUR INSPECTION, THE MECHANIC NOTICED A TEAR IN THE RIGHT SIDE OF THE NOSE GEAR WHEELWELL SKIN UNDER THE DOWNLOCK HINGE BRACKET (CESSNA BRACKET PART 0842105-2). THE DOUBLER THAT ATTACHES TO THE SKIN/BACKET ASSEMBLY (DOUBLER CESSNA PART 5213045-2) WAS ALSO CRACKED/BROKEN. SUBMITTER STATED THIS PROBLEM IS MOST COMMONLY FOUND ON THE LEFT SIDE, THE ABOVE MENTIONED BRACKET ON THE LEFT SIDE ACTUATES OR CYCLES THE GEAR. THE PROBLEM COULD BE ASSOCIATED WITH ICE BUILDING (OR FORMING) ON THE LEADING EDGES OF GEAR DOORS CAUSING A PARTIAL BIND WHEN TRYING TO CYCLE THE GEAR.								
3244	2427W	PIPER			MCCREARY	TIRE	CHAFED		12/19/97
	311104005	PA31T1			65010	30855	MLG		98ZZZX358
*****	INSTALLED TIRE ON WHEEL, NOTICED MINIMUM CLEARANCE ON SIDEWALL TIRE HAS TWO GROOVES CUT IN IT BY THE BRAKES. SUBMITTER STATED TIRE IS A DIFFERENT SHAPE THAN A GOODYEAR TIRE.								

(End of GENERAL AVIATION SIGNIFICANT OCCURRENCE REPORT)

**FEDERAL AVIATION ADMINISTRATION**  
**SIGNIFICANT OCCURRENCE REPORT INDEX**

Showing Specific Part Numbers and Aircraft Model by Year

FOR THE PERIOD OF: 1/25/98 To 1/31/98


<u>PART NUMBER</u>			<u>YEAR</u>											
<u>PART NAME</u>	<u>ACFT MODEL</u>	<u>TOTAL</u>	<u>1987</u>	<u>1988</u>	<u>1989</u>	<u>1990</u>	<u>1991</u>	<u>1992</u>	<u>1993</u>	<u>1994</u>	<u>1995</u>	<u>1996</u>	<u>1997</u>	<u>1998</u>
<b>15703014</b>														
DIMMER ASSY	172R	<u>1</u>	-	-	-	-	-	-	-	-	-	-	-	1
<b>TOTAL of # 15703014</b> - - - - -		<u>1</u>	-	-	-	-	-	-	-	-	-	-	-	1
<b>222031056103</b>														
BULKHEAD	222U	<u>1</u>	-	-	-	-	-	-	-	-	-	-	-	1
<b>TOTAL of # 222031056103</b> - - - - -		<u>1</u>	-	-	-	-	-	-	-	-	-	-	-	1
<b>30855</b>														
TIRE	PA31T1	<u>1</u>	-	-	-	-	-	-	-	-	-	-	-	1
<b>TOTAL of # 30855</b> - - - - -		<u>1</u>	-	-	-	-	-	-	-	-	-	-	-	1
<b>51590000</b>														
ACM	JETSTM3201	<u>1</u>	-	-	-	-	-	-	-	-	-	-	-	1
<b>TOTAL of # 51590000</b> - - - - -		<u>1</u>	-	-	-	-	-	-	-	-	-	-	-	1
<b>52130452</b>														
DOUBLER	402B	<u>1</u>	-	-	-	-	-	-	-	-	-	-	-	1
	414	<u>2</u>	-	-	-	-	-	-	-	-	-	-	1	1
	421B	<u>1</u>	-	-	-	-	-	-	1	-	-	-	-	-
SUPPORT	404CESSNA	<u>1</u>	-	-	-	-	1	-	-	-	-	-	-	-
<b>TOTAL of # 52130452</b> - - - - -		<u>5</u>	-	-	-	-	1	-	1	-	-	-	1	2
<b>67420607</b>														
STRUT	750	<u>1</u>	-	-	-	-	-	-	-	-	-	-	-	1
<b>TOTAL of # 67420607</b> - - - - -		<u>1</u>	-	-	-	-	-	-	-	-	-	-	-	1
<b>W31X2M1620</b>														
BREAKER	340A	<u>1</u>	-	-	-	-	-	-	-	-	-	-	-	1
<b>TOTAL of # W31X2M1620</b> - - - - -		<u>1</u>	-	-	-	-	-	-	-	-	-	-	-	1

FAA SIGNIFICANT OCCURRENCE REPORT INDEX 1/25/98 To 1/31/98 (cont'd)

PART NUMBER		YEAR												
PART NAME	ACFT MODEL	TOTAL	1987	1988	1989	1990	1991	1992	1993	1994	1995	1996	1997	1998
TOTAL for ALL (10) PART NUMBERS: - - - -		11	-	-	-	-	1	-	1	-	-	-	1	8
END OF SIGNIFICANT OCCURRENCE REPORT INDEX														



# **DOMESTIC SERVICE DIFFICULTY REPORT**





**DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT****1/25/98 - 1/31/98    ISSUE: 98-05    ZAC-327**

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
3340	72567 E2280	BEECH A36				WIRE	SHORTED NAV LIGHT	1272	1/9/98 98ZZZX353
RT NAVIGATION LIGHT POWER WIRE ROUTED THROUGH WING ALONG CHANNEL UNDER TOP WING SKIN. NOTHING TO SECURE WIRE IN PLACE AND NO CHAFE PROTECTION PROVIDED. WIRE CAME OUT OF CHANNEL, CHAFED ON RIB EVENTUALLY CAUSING A SHORT AND BURNED WIRE IN TWO. INSPECTION OF LT SIDE REVEALED SAME PROBLEM, BUT HAS NOT CHAFED THROUGH YET. PROBLEM RESOLVED BY ADDING CHAFE PROTECTION AND RE-ROUTING WIRE. THIS AREA CANNOT BE INSPECTED WITHOUT REMOVING WING TIP.									
3244	228RA LW197	BEECH E90				TIRE 65X10	IMBALANCE NLG	66	1/9/98 98ZZZX338
TIRE SUDDENLY BECAME UNBALANCED DUE TO THE RUBBER BALANCE PATCH ON THE INTERIOR BECOMING DETACHED. SUBMITTER STATED MANUFACTURER'S DEFECT. 92 LANDINGS, 1.8 MONTHS IN SERVICE. NORMAL OPERATING CONDITIONS.									
3244	987GM LW65	BEECH E90				TIRE 850X10	IMBALANCE MLG	185	1/9/98 98ZZZX342
TIRE SUDDENLY BECAME UNBALANCED DUE TO THE RUBBER BALANCE PATCH ON THE INTERIOR BECOMING DETACHED UNDER NORMAL CONDITIONS, 281 LANDINGS, 185 HOURS, 3.7 MONTHS IN SERVICE. SUBMITTER STATED MANUFACTURER'S DEFECT.									
3310 N3XR *****	403ER 17280245	CESSNA 172R				DIMMER ASSY 15703014	MISWIRED INST LIGHTS	34	12/1/97 98ZZZX359
DURING A TRAINING FLIGHT, THE CREW SMELLED A BURNING SCENT. AFTER FOLLOWING THE EMERGENCY CHECKLIST, THEY WERE GOING TO LAND OFF-FIELD. THE SMELL DIMINISHED AND THEY PROCEEDED TO X-47. DURING THE FOLLOWING INSPECTION, A RESISTOR WAS FOUND BURNED IN HALF ON THE DIMMER ASSY. IT WAS DISCOVERED THE UNIT IS WIRED INCORRECTLY. IT APPEARS TO BE A FLEET PROBLEM. AFTER A CALL TO CESSNA, DISABLED THE DIMMERS IN THE ENTIRE FLEET. SB 97-33-01 APPLIES.									
5720	1682C 30382	CESSNA 180				BEARING BLOCK 0512122	CORRODED RT AFT BLOCK	3706	12/31/97 98ZZZX344
RIGHT REAR BLOCK IN REAR CARRY-THROUGH BULKHEAD CORRODED IN BOLT HOLE AND INTERGRANULAR CORROSION IN BLOCK.									
2434	86109 18503153	CESSNA A185F	CONT IO520D		FORD	ALTERNATOR 315	FAILED DC SYSTEM	1/15/98 699	98ZZZX354
ALTERNATOR QUIT WORKING. FOUND BRUSHES TOTALLY WORN OUT.									
2434	4640E 18503824	CESSNA A185F			FORD	ALTERNATOR 318	FAILED DC SYSTEM	1/14/98 563	98ZZZX350
ALTERNATOR FAILED. FOUND BRUSHES COMPLETELY WORN OUT.									
2434	61423 18504180	CESSNA A185F			FORD	ALTERNATOR 318	FAILED DC SYSTEM	1/15/98 609	98ZZZX352
ALTERNATOR FAILED. FOUND BRUSHES COMPLETELY WORN OUT.									
3260	5515Y 21064233	CESSNA T210N				SWITCH YZ2RN7T	CRACKED NLG UPLOCK	12/1/97	98ZZZX356
NOSE GEAR UPLOCK SWITCH PLUNGER CRACKS AT INSERT (PLASTIC). SECOND AIRCRAFT IN LAST YEAR WITH THIS PROBLEM DISCOVERED DURING ANNUAL INSPECTION. THIS CRACKING PERMITS MOISTURE INSIDE THE HOUSING CAUSING ERRONEOUS UNLOCK INDICATIONS IN COCKPIT WHEN GEAR IS ACTUALLY UP AND LOCKED.									
5512 *****	732XE 2061850	CESSNA T210M			123260029	RIB	CRACKED H STAB LT/RT	3197	1/7/98 98ZZZX318
DURING ANNUAL INSPECTION, A CLICKING NOISE WAS HEARD WHILE PRESSING THE LEADING EDGE OF THE HORIZONTAL STABILIZER AT THE RIBS. WITH FURTHER INSPECTION, SEVERAL RIBS FOUND CRACKED ON BOTH LT AND RT SIDES OF THE STABILIZER. ALSO, FOUND ON THIS ACFT, RIB PN 1232105-1 HAS BEEN BENT. THIS IS 3RD T210 THAT HAS BEEN FOUND WITH CRACKED LEADING EDGE RIBS AND ALSO FOUND SEVERAL TU206 ACFT WITH THIS SAME CONDITION. IT APPEARS THAT YEARS OF PUSHING ON STAB DURING GROUND HANDLING HAS HELPED TO CREATE THIS CONDITION. TT ON ALL ACFT IS APPROXIMATELY 3,000 HRS.									

\*\*\*\*\* DENOTES SIGNIFICANT OCCURRENCE

## DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT (cont'd)

1/25/98 To 1/31/98 ISSUE: 98-05 ZAC-327

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
3060	340MT	CESSNA				BREAKER	FAILED		12/15/97
	340A0741	340A				W31X2M1620	PROPELLER DEICE		98ZZZX349
*****	PROPELLER DE-ICE WAS SELECTED ON AIRCRAFT CLIMBING THROUGH SNOW FLURRIES. THE PROPELLER DE-ICE PIGTAIL WIRES AT PROPELLER HUB WERE SHORTED TO THE SPINNER. THIS CAUSED SMOKE IN THE COCKPIT. AIRCRAFT RETURNED AND MADE AN UNEVENTFUL LANDING. THE PROPELLER DE-ICE CIRCUIT BREAKER DID NOT TRIP TO THE OFF OR OPEN POSITION ALLOWING THE WIRING FROM THE CIRCUIT BREAKER TO THE DE-ICE GAUGE TO BURN IN TWO.								
5320	29MM	CESSNA				DOUBLER	CRACKED	7936	12/15/97
HBCA	402B0863	402B				52130452	NLG RT WELL SKIN		98ZZZX347
*****	DURING A 100-HOUR INSPECTION, THE MECHANIC NOTICED A TEAR IN THE RIGHT SIDE OF THE NOSE GEAR WHEELWELL SKIN UNDER THE DOWNLOCK HINGE BRACKET (CESSNA BRACKET PART 0842105-2). THE DOUBLER THAT ATTACHES TO THE SKIN/BACKET ASSEMBLY (DOUBLER CESSNA PART 5213045-2) WAS ALSO CRACKED/BROKEN. SUBMITTER STATED THIS PROBLEM IS MOST COMMONLY FOUND ON THE LEFT SIDE, THE ABOVE MENTIONED BRACKET ON THE LEFT SIDE ACTUATES OR CYCLES THE GEAR. THE PROBLEM COULD BE ASSOCIATED WITH ICE BUILDING (OR FORMING) ON THE LEADING EDGES OF GEAR DOORS CAUSING A PARTIAL BIND WHEN TRYING TO CYCLE THE GEAR.								
8120	5040Q	CESSNA				BRACKET	BROKEN		12/15/97
HBCA	402B0347	402B				08511393	RT TURBO MOUNT		98ZZZX351
	DURING A 100-HOUR INSPECTION, MECHANIC FOUND THE RIGHT TURBO MOUNTING BRACKET BROKEN. CESSNA BRACKET 0851139-3 HAD ITS OUTBOARD LOWER ATTACH LEG BROKEN OFF. UNABLE TO DETERMINE THE CAUSE OF THIS PROBLEM.								
7931	500UB	GULSTM				SWITCH	LEAKING	2685	12/22/97
BXSR	5600052	560				98087	LT ENG OIL PRESS		98ZZZX316
	LARGE AMOUNTS OF OIL WERE LEAKING FROM THE RT ENGINE. FOUND THE OIL PRESSURE SWITCH INTERNAL SEAL HAD FAILED.								
5711	2013B	LUSCOM				SPAR	CORRODED	3599	1/2/98
	6440	8A				0822031	WING ROOT		98ZZZX346
	DURING ACCOMPLISHMENT OF AD 96-24-17 (AMEND NR 39-9841 EFF 1-27-97) INTERGRANULAR CORROSION WAS FOUND ON THE REAR SPAR APPROXIMATELY 12 INCHES OUTBOARD OF WING ATTACH POINTS ON THE REAR SURFACE TOP OF REAR SPAR. AREA WAS SLIGHTLY BULGED WITH A .50 INCH IN DIAMETER PIT WITH FLAKING ALUMINUM INSIDE THE DEFECT.								
5751	1895B	LUSCOM				HINGE FITTING	MISMANUFACTURED		12/31/97
FE6R	6322	8F			U582731	U18279	RT AIL CENTER		98ZZZX345
	A NEW FAA PMA RIGHT AILERON IS PURCHASED FROM UNIVAIR AIRCRAFT FOR INSTALLATION ON AIRCRAFT. THE AILERON WOULD NOT FIT ON THE AIRCRAFT AS RECEIVED DUE TO MISALIGNMENT OF THE CENTER HINGE FITTING. NO OTHER AILERON WAS AVAILABLE FROM THIS MANUFACTURER. THE MANUFACTURER SHIPPED AN UNDRILLED CENTER HINGE FITTING P/N U18279 WHICH WAS INSTALLED ON THE NEW AILERON. SUBSEQUENT OPERATION WAS NORMAL.								
5310	6410Z	PIPER				FRAME	CORRODED	3006	1/9/97
	25546	PA25					FUSELAGE		98ZZZX312
	CORROSION AT TUBING CLUSTER 27 INCHES AFT OF FIREWALL ON LOWER LONGERON. GUSSETS SUPPORTING THE VERTICAL MEMBER HAD ALLOWED DEBRIS AND MOISTURE TO COLLECT ON LONGERON. LONGERON WAS PERFORATED BY RUST FORE AND AFT OF VERTICAL MEMBER ON RT SIDE. A SMALLER PERFORATION EXISTED IN FRONT OF VERTICAL MEMBER ON LT SIDE. GUSSET AREA APPARENTLY FILLED WITH A SEALANT AT TIME OF MFG. THIS HAD BEEN REMOVED AND RTV SUBSTITUTED IN ITS PLACE. SUBMITTER BELIEVES CORROSION EXISTED PRIOR TO RTV APPLICATION.								
3244	2427W	PIPER			MCCREARY	TIRE	CHAFED		12/19/97
	311104005	PA31T1			65010	30855	MLG		98ZZZX358
*****	INSTALLED TIRE ON WHEEL, NOTICED MINIMUM CLEARANCE ON SIDEWALL TIRE HAS TWO GROOVES CUT IN IT BY THE BRAKES. SUBMITTER STATED TIRE IS A DIFFERENT SHAPE THAN A GOODYEAR TIRE.								

(End of DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT)

**DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS****1/25/98 - 1/31/98    ISSUE: 98-05    ZAC-327**

<b>ATA OPER</b>	<b>REG. NO SERIAL NO</b>	<b>ACFT MAKE ACFT MODEL</b>	<b>ENG MAKE ENG MDL</b>	<b>PROP MAKE PROP MDL</b>	<b>COMP MFG COMP MDL</b>	<b>PART NAME PART NUMBER</b>	<b>PART COND PART LOC.</b>	<b>TT TSO</b>	<b>DIFF. DATE OPER CONT NO</b>
3340 TI1R	206MH 45426	BELL 206L				SEARCH LIGHT SX5	FAILED NOSE SECTION		12/4/97 98ZZZX367
SEARCH LIGHT TURNS OFF IN-FLIGHT AND SOMETIMES WILL NOT RE-START. REMOVED AND REPLACED.									
3453 TI1R	206MH 45426	BELL 206L			KLN89	LORAN 066011481111	CRACKED FACEPLATE		12/4/97 98ZZZX329
LORAN FACE PLATE DISPLAY CRACKED. REMOVED AND REPLACED.									
7323 LS1R	9907K 2040	BELL 206B	ALLSN 250C20			GOVERNOR 252466712	FAILED ENGINE PT	1576	1/6/98 98ZZZX323
GOVERNOR SLOW TO RESPOND TO POWER CHANGES (HIGH AND LOW SIDE).									
7323 TI1R	206MH 45426	BELL 206L	ALLSN 250C28B		23004545	GOVERNOR 23004836	FAILED ENGINE	236	12/1/97 98ZZZX330
GOVERNOR REMOVED FOR TORQUE SPIKES WITH POWER CHANGES. COMPONENT OF ENGINE 23004545, S/N CAE890566. REMOVED AND REPLACED.									
7532 TI1R	721SP 45486	BELL 206L	ALLSN 250C30			BLEED VALVE 23005366	FAILED ENGINE	618	11/17/97 98ZZZX336
ENGINE HAD COMPRESSOR STALL AT LOW POWER. REMOVED AND REPLACED BLEED VALVE.									
5312 RMXA *****	222HX 47533	BELL 222U				BULKHEAD 222031056103	CRACKED BS 270		1/14/98 98ZZZX324
FOUND 2 EACH CRACKS IN AFT MAIN ROOF BEAM AT LT NODAL BEAM SUPPORT. BS 270, WL 79.0, LBL 9.90.									
2312 TI1R	495LF S645	BOLKMS BO105S			KY196	TRANSCIEVER 064101900	MALFUNCTION COCKPIT		12/4/97 98ZZZX334
UNABLE TO AJDUST SIDE TONE/MIC GAIN DOWN TO A SUITABLE LEVEL TO MATCH OUTPUT OF OTHER AVIONICS EQUIPMENT. REMOVED AND REPLACED.									
3425 TI1R	117LU 7144	BOLKMS BK117B1				INDICATOR 5204210002	FAILED HSI		12/21/97 98ZZZX365
HSI INDICATOR ROTATES CLOCKWISE. REMOVED AND REPLACED.									
3453 TI1R	460H 7142	BOLKMS BK117B1			612B	LORAN 4309805000	FAILED COCKPIT		11/10/97 98ZZZX333
LORAN HEADINGS AND MILEAGE INCORRECT. RE: RMA 652062. REMOVED AND REPLACED.									
3610 TI1R	527MB 7103	BOLKMS BK117A3				VALVE 97914211	FAILED BLEED SOV		12/8/97 98ZZZX335
VALVE INOPERATIVE. REMOVED AND REPLACED.									
3120 TI1R	317MC 7505	BOLKMS BK117C1				CLOCK JB15307	FAILED COCKPIT		11/19/97 98ZZZX368
CLOCK LOSES TIME, RUNS SLOW. REMOVED AND REPLACED.									
3213 TI1R	317MC 7505	BOLKMS BK117C1				SKID 1175000211	WORN GEAR SKID		10/18/97 98ZZZX332
SKID PROTECTIVE WORN BEYOND LIMITS. REMOVED AND REPLACED.									

\*\*\*\*\* DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

1/25/98 To 1/31/98    ISSUE: 98-05    ZAC-327

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
3213 TI1R	317MC 7505	BOLKMS BK117C1				SKID 1175000212	WORN GEAR SKID		10/18/97 98ZZZX331
PROTECTIVE SKID WORN BEYOND LIMITS. REMOVED AND REPLACED.									
3421 TI1R	117NC 7509	BOLKMS BK117C1				HORIZON 4021541671	FAILED COCKPIT		12/4/97 98ZZZX366
INOPERABLE FOR P/R CSAS SYSTEM. REMOVED AND REPLACED.									
6710 TI1R	117NC 7509	BOLKMS BK117C1				BRACKET 1174123101	BROKEN CYLIC	393	11/25/97 98ZZZX328
BRACKET WELDS BROKE. REMOVED AND REPLACED.									
(End of DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS)									

**DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - ENGINES****1/25/98 - 1/31/98    ISSUE: 98-05    ZAC-327**

<b>ATA OPER</b>	<b>REG. NO SERIAL NO</b>	<b>ACFT MAKE ACFT MODEL</b>	<b>ENG MAKE ENG MDL</b>	<b>PROP MAKE PROP MDL</b>	<b>COMP MFG COMP MDL</b>	<b>PART NAME PART NUMBER</b>	<b>PART COND PART LOC.</b>	<b>TT TSO</b>	<b>DIFF. DATE OPER CONT NO</b>
7323	566CA	BEECH	PWA		BENDIX	GOVERNOR	FAILED		1/9/98
	LJ184	65A90	PT6A20			25241673	ENGINE	3600	98ZZZX317
POWER TURBINE GOVERNOR FLYWEIGHTS AND BUSHING FAILED CAUSING GOVERNOR TO DUMP PY AIR TO FUEL CONTROL UNIT ALLOWING POWER TO DROP TO 50 PERCENT. ENGINE WAS FEATHERED AND RETURNED TO HOME BASE WHERE GOVERNOR WAS REPLACED WITH OVERHAULED UNIT AND CHECKED OPERATION AND FLIGHT TEST.									
7323	9907K	BELL	ALLSN			GOVERNOR	FAILED		1/6/98
LS1R	2040	206B	250C20			252466712	ENGINE PT	1576	98ZZZX323
GOVERNOR SLOW TO RESPOND TO POWER CHANGES (HIGH AND LOW SIDE).									
7323	206MH	BELL	ALLSN			GOVERNOR	FAILED	236	12/1/97
TI1R	45426	206L	250C28B		23004545	23004836	ENGINE		98ZZZX330
GOVERNOR REMOVED FOR TORQUE SPIKES WITH POWER CHANGES. COMPONENT OF ENGINE 23004545, S/N CAE890566. REMOVED AND REPLACED.									
7532	721SP	BELL	ALLSN			BLEED VALVE	FAILED	618	11/17/97
TI1R	45486	206L	250C30			23005366	ENGINE		98ZZZX336
ENGINE HAD COMPRESSOR STALL AT LOW POWER. REMOVED AND REPLACED BLEED VALVE.									
8530	6822U	CESSNA	CONT			SPRING SEAT	BROKEN		1/16/98
	414A0808	414A	TSIO520NB				ENG EXH VALVE		98ZZZX357
REMOVED ROCKER COVER TO INSPECT FOR AD APPLICABILITY AND FOUND PARTICLES OF SPRING SEAT LAYING IN BOTTOM OF ROCKER COVER. DISASSEMBLED EXHAUST VALVE SPRING. FOUND SEAT BROKEN AROUND INNER RADIUS. SUBMITTER STATED EXHAUST VALVE GUIDE APPEARED TO BE .0625 INCH FARTHER OUT OF HEAD THAN REQUIRED. APPEARED AS IF VALVE GUIDE HAD WORKED LOOSE IN HEAD.									
8530	31754	PIPER	LYC			CYLINDER	CRACKED	1546	1/6/98
	287890478	PA28181	O360A4M			LW12427	NR 4		98ZZZX348
PILOT EXPERIENCED ROUGH ENGINE OPERATION AND RETURNED TO AIRPORT WITH UNEVENTFUL LANDING. INSPECTION BY MAINTENANCE PERSONNEL DISCOVERED NR 4 CYLINDER HAD ZERO COMPRESSION. CYLINDER WAS REMOVED AND FORWARDED TO ENGINE OVERHAUL SHOP WHERE FURTHER INSPECTION REVEALED CYLINDER WAS CRACKED APPROXIMATELY HALF WAY AROUND CIRCUMFERENCE BETWEEN CYLINDER BORE TO HEAD THREAD. NO HISTORY OF OPERATIONAL PROBLEMS WITH EITHER THIS CYLINDER OR OTHERS MOUNTED TO THIS ENGINE.									
8520	9504K	UNIVAR	FRNKLN			CRANKSHAFT	CRACKED	406	12/2/97
	1082504	1082	6A4165B3			18486	PROP FLANGE		98ZZZX313
INSPECTION FOUND CRANKSHAFT PROPELLER FLANGE CRACKED BETWEEN HOLES IN TWO PLACES.									

**(End of DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - ENGINES)**

**DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - COMPONENTS****1/25/98 - 1/31/98    ISSUE: 98-05    ZAC-327**

<b>ATA OPER</b>	<b>REG. NO SERIAL NO</b>	<b>ACFT MAKE ACFT MODEL</b>	<b>ENG MAKE ENG MDL</b>	<b>PROP MAKE PROP MDL</b>	<b>COMP MFG COMP MDL</b>	<b>PART NAME PART NUMBER</b>	<b>PART COND PART LOC.</b>	<b>TT TSO</b>	<b>DIFF. DATE OPER CONT NO</b>
3453 TI1R	206MH 45426	BELL 206L			KLN89	LORAN 066011481111	CRACKED FACEPLATE		12/4/97 98ZZZX329
LORAN FACE PLATE DISPLAY CRACKED. REMOVED AND REPLACED.									
2312 TI1R	495LF S645	BOLKMS BO105S			KY196	TRANSCEIVER 064101900	MALFUNCTION COCKPIT		12/4/97 98ZZZX334
UNABLE TO AJDUST SIDE TONE/MIC GAIN DOWN TO A SUITABLE LEVEL TO MATCH OUTPUT OF OTHER AVIONICS EQUIPMENT. REMOVED AND REPLACED.									
3425 TI1R	117LU 7144	BOLKMS BK117B1				INDICATOR 5204210002	FAILED HSI		12/21/97 98ZZZX365
HSI INDICATOR ROTATES CLOCKWISE. REMOVED AND REPLACED.									
3453 TI1R	460H 7142	BOLKMS BK117B1			612B	LORAN 4309805000	FAILED COCKPIT		11/10/97 98ZZZX333
LORAN HEADINGS AND MILEAGE INCORRECT. RE: RMA 652062. REMOVED AND REPLACED.									
3120 TI1R	317MC 7505	BOLKMS BK117C1				CLOCK JB15307	FAILED COCKPIT		11/19/97 98ZZZX368
CLOCK LOSES TIME, RUNS SLOW. REMOVED AND REPLACED.									
3421 TI1R	117NC 7509	BOLKMS BK117C1				HORIZON 4021541671	FAILED COCKPIT		12/4/97 98ZZZX366
INOPERABLE FOR P/R CSAS SYSTEM. REMOVED AND REPLACED.									
6122 LU4R	3878T 28R30203	PIPER PA28R180			HARTZL F27A	DRIVE GEAR C4191	DEFECTIVE PROPELLER GOV	3940	1/6/98 98ZZZX361
GOVERNOR DRIVE GEAR HAS SHARP INDICATION AT BASE OF TOOTH EXTENDING AROUND CORNER.									

**(End of DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - COMPONENTS)**

**DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - PROPELLERS**


**1/25/98 - 1/31/98    ISSUE: 98-05    ZAC-327**

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
6110 LU4R	9EF 277305092	PIPER PA23250		HARTZL HCE2YR2		BEARING	CRACKED PROP ASSY	2592	1/5/98 98ZZZX364
INSPECTION FOUND PROPELLER ASSY BEARING CRACKED.									
6110 LU4R	4414K NAV41414	TMPSON NAVION*		HARTZL HCA2X204		GUIDE COLLAR C2222	CRACKED PROPELLER	1646	1/6/98 98ZZZX360
PROPELLER COLLAR GUIDE PARTS HAD CRACKS EXTENDING UP TO 1.5 INCHES ORIGINATING AT THREADED HOLE AND EXTENDING AROUND CORNERS. PROPELLER HAD NOT BEEN REMOVED FROM AIRCRAFT SINCE INSTALLED IN MARCH, 1973.									

**(End of DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - PROPELLERS)**



# **INTERNATIONAL SERVICE DIFFICULTY REPORT**





**INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT**

**1/25/98 - 1/31/98    ISSUE: 98-05    ZAC-327**

ATA	REG. NO	ACFT MAKE	ENG MAKE	PROP MAKE	COMP MFG	PART NAME	PART COND	TT	DIFF. DATE
OPER	SERIAL NO	ACFT MODEL	ENG MDL	PROP MDL	COMP MDL	PART NUMBER	PART LOC.	TSO	OPER CONT NO

(There was no data for this report.)

(End of INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT)

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
8500		HUGHES 269C	LYC HO360*			ENGINE	FAILED POWER PLANT		11/7/97 AU971471

(AUS) ENGINE SUFFERED A POWER LOSS FOLLOWED BY A STOPPAGE. AIRCRAFT CRASHED.

(End of INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS)

**INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - ENGINES**

**1/25/98 - 1/31/98    ISSUE: 98-05    ZAC-327**

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
7414		BEECH 76	LYC O360A1G		BENDIX IO382754	SPRING IO51324	BROKEN RT ENG MAG		12/3/97 1414    AU971522
(AUS) RH ENGINE MAGNETO IMPULSE COUPLING SPRING BROKEN.									
8500		HUGHES 269C	LYC HO360*			ENGINE	FAILED POWER PLANT		11/7/97 AU971471
(AUS) ENGINE SUFFERED A POWER LOSS FOLLOWED BY A STOPPAGE. AIRCRAFT CRASHED.									
(End of INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - ENGINES)									

ATA	REG. NO	ACFT MAKE	ENG MAKE	PROP MAKE	COMP MFG	PART NAME	PART COND	TT	DIFF. DATE
OPER	SERIAL NO	ACFT MODEL	ENG MDL	PROP MDL	COMP MDL	PART NUMBER	PART LOC.	TSO	OPER CONT NO

(There was no data for this report.)

(End of INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - COMPONENTS)

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
6111		BEECH	PWA	MCAULY		BLADE	FOD		10/21/97
		B200C	PT6A42	3GFR34C701			LT PROP TIP		AU971439
	(AUS) LH PROPELLER BLADE TIP BENT. BLOOD ON THE BLADE LEADS TO THE ASSUMPTION OF AND ANIMAL STRIKE.								
6114		PIPER	LYC	HARTZL		HUB	CRACKED		12/10/97
		PA36300	IO540K1G5	HCC2YK1		22117	PROP HUB		AU971571
	(AUS) PROPELLER HUB WAS PREVIOUSLY INSPECTED AT THE 50HR INTERVAL IAW HARTZELL SB164C AND FOUND SATISFACTORY. WHEN INSPECTED AT THE 100 HOURLY, A PARTICULARLY LARGE CRACK WAS FOUND IN THE REAR HALF OF THE RADIUS AT THE BLADE ROOT.								

(End of INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - PROPELLERS)



U.S. Department  
of Transportation  
**Federal Aviation  
Administration**

## **SERVICE DIFFICULTY REPORT SUMMARY**

### **GENERAL AVIATION - INDEX**



The following information provides a tally of the Service Difficulty Reports (SDR's) contained in this weeks issue of the General Aviation SDR Summary. The totals represent only a summation of the SDR's that were submitted to the FAA, Aviation Data Systems Branch, AFS-620, and processed in time for inclusion in the Summary. The first table is a tally of the number of SDR's submitted through the indicated Flight Standards District Office (FSDO). The second table sorts the SDR's by the aircraft or equipment make and model. The heading at the top of each table provides a two digit Joint Aircraft System/Component (JASC) code grouping (e.g., JASC codes 1100 thru 1800 are represented by the heading labeled 11-18) which categorizes in general, the problem areas for each reported discrepancy.

The Flight Standards Service Difficulty Program objective is to achieve prompt and appropriate correction of conditions adversely affecting continued airworthiness of aeronautical products. This is accomplished by the collection of Service Difficulty and Malfunction or Defect Reports. SDR's are consolidation and collation into common data base where they are analyzed for trends, problems, and alert information. This information is then disseminated to the appropriate segments of the aviation community and to other FAA offices.

The number of SDR's submitted is not an indicator of the mechanical reliability or fitness of an air carrier's aircraft fleet and should not be used as such. The air carriers certificate holding office has the primary responsibility for planning, programming evaluations, and assessing the performance of operators. Questions regarding an air carrier's fleet performance should be directed to the appropriate Flight Standards District Office, Certificate Management Office, or Certificate Management Unit.

**GENERAL AVIATION SUMMARY INDEX BY DISTRICT OFFICE****1/25/98 To 1/31/98    ISSUE: 98-05    ZAC-327**

DISTRICT OFFICE		SDR TOTALS BY FAA ATA SYSTEM CHAPTER								TOTAL
		11-18	21-29	30-38	45-49	51-57	61-67	71-79	80-85	
AL	03	0	0	0	0	1	0	0	0	1
AU	S	0	0	0	0	0	2	1	1	4
CE	01	0	0	0	0	0	0	1	0	1
EA	09	0	0	0	0	0	0	1	0	1
EA	11	0	0	0	0	0	0	0	1	1
EA	13	0	0	0	0	0	0	1	0	1
EA	23	0	0	0	0	1	0	0	0	1
EA	27	0	0	1	0	0	0	0	0	1
GL	11	0	0	1	0	0	0	0	0	1
GL	15	0	0	0	0	0	0	0	1	1
NE	05	0	0	0	0	0	0	0	1	1
NM	11	0	3	0	0	2	0	0	0	5
SO	13	0	0	1	0	0	0	0	0	1
SO	15	0	0	1	0	0	0	0	0	1
SO	16	0	0	1	0	0	0	0	0	1
SO	17	0	0	0	0	0	3	0	0	3
SW	05	0	1	9	0	1	1	2	0	14
SW	11	0	0	0	0	1	0	0	1	2
WP	07	0	0	2	0	1	0	0	0	3
<b>TOTALS</b>		<b>0</b>	<b>4</b>	<b>16</b>	<b>0</b>	<b>7</b>	<b>6</b>	<b>6</b>	<b>5</b>	<b>44</b>

---

---

(End of GENERAL AVIATION SUMMARY INDEX by DISTRICT OFFICE Report)

**GENERAL AVIATION SUMMARY INDEX by MANUFACTURER MAKE and MODEL****1/25/98 To 1/31/98    ISSUE: 98-05    ZAC-327**

AIRCRAFT MAKE	AIRCRAFT MODEL	SDR TOTALS BY FAA ATA SYSTEM CHAPTER								TOTAL
		11-18	21-29	30-38	45-49	51-57	61-67	71-79	80-85	
BEECH	65A90	0	0	0	0	0	0	1	0	1
BEECH	76	0	0	0	0	0	0	1	0	1
BEECH	A36	0	0	1	0	0	0	0	0	1
BEECH	B200C	0	0	0	0	0	1	0	0	1
BEECH	E90	0	0	2	0	0	0	0	0	2
BELL	206B	0	0	0	0	0	0	1	0	1
BELL	206L	0	0	2	0	0	0	2	0	4
BELL	222U	0	0	0	0	1	0	0	0	1
BOLKMS	BK117A3	0	0	1	0	0	0	0	0	1
BOLKMS	BK117B1	0	0	2	0	0	0	0	0	2
BOLKMS	BK117C1	0	0	4	0	0	1	0	0	5
BOLKMS	BO105S	0	1	0	0	0	0	0	0	1
CESSNA	172R	0	0	1	0	0	0	0	0	1
CESSNA	180	0	0	0	0	1	0	0	0	1
CESSNA	340A	0	0	1	0	0	0	0	0	1
CESSNA	402B	0	0	0	0	1	0	0	1	2
CESSNA	414A	0	0	0	0	0	0	0	1	1
CESSNA	A185F	0	3	0	0	0	0	0	0	3
CESSNA	T210M	0	0	0	0	1	0	0	0	1
CESSNA	T210N	0	0	1	0	0	0	0	0	1
GULSTM	560	0	0	0	0	0	0	1	0	1
HUGHES	269C	0	0	0	0	0	0	0	1	1
LUSCOM	8A	0	0	0	0	1	0	0	0	1
LUSCOM	8F	0	0	0	0	1	0	0	0	1
PIPER	PA23250	0	0	0	0	0	1	0	0	1
PIPER	PA25	0	0	0	0	1	0	0	0	1
PIPER	PA28181	0	0	0	0	0	0	0	1	1



AIRCRAFT MAKE	AIRCRAFT MODEL	SDR TOTALS BY FAA ATA SYSTEM CHAPTER								
		11-18	21-29	30-38	45-49	51-57	61-67	71-79	80-85	TOTAL
PIPER	PA28R180	0	0	0	0	0	1	0	0	1
PIPER	PA31T1	0	0	1	0	0	0	0	0	1
PIPER	PA36300	0	0	0	0	0	1	0	0	1
TMPSON	NAVION*	0	0	0	0	0	1	0	0	1
UNIVAR	1082	0	0	0	0	0	0	0	1	1
TOTALS		0	4	16	0	7	6	6	5	44

(End of AIR CARRIER SUMMARY INDEX by OPERATOR Report)

# JOINT AIRCRAFT SYSTEM/COMPONENT CODE TABLE

## PREFACE

The Joint Aircraft System/Component (JASC) Code Table is a modified version of the Air Transport Association of America (ATA), Specification 100 code. It was developed by the Federal Aviation Administration's (FAA), Aviation Data Systems Branch (AFS-620). Technical support was provided by the Galaxy Scientific Corporation, and various representatives of the air carrier and general aviation community.

Over the past four years, the JASC format of the ATA Spec 100 code has gained widespread industry acceptance. In a harmonized effort, the FAA's counterparts in Australia and Canada have adopted the JASC code with only a few exceptions. Some Canadian aircraft manufacturers have also recently adopted this new standard.

This code table is constructed by using the new JASC four (4) digit code, along with an abbreviated code title. The abbreviated titles have been modified in some cases to clarify the intended use of the accompanying code. This table can be used as a quick reference chart, to assist in the coding and review of aircraft structures or systems data (i.e., Service Difficulty Report (SDR), Accident/Incident Report).

The current coding scheme used in the JASC code was introduced in May 1991, for the technical classification of SDR's. Its predecessor, the FAA aircraft system/component code, was a similar but more complex eight-digit code which was developed over 25 years ago. It was constructed around the computer technology of that period. It consisted of a four digit numerical code plus a four alpha character code to make data retrieval possible. Since that time, computer technology has advanced many fold. Reducing the code from eight to four characters simplifies coding, and in some cases, makes JASC coding match the ATA Specification 100 first three digits, which are used to identify aircraft systems. The ATA code does not reference the fourth digit, so it is free to be used for identifying components.

The JASC code aircraft structural section has increased due to problems inherent with aging aircraft. As an example, FAA code 5301 SXBD was expanded to 20 items due to the high rate of reporting in this area (8021 structural reports were received in 1989). In some instances, there was very little reporting and codes were combined into other systems if the safety impact was not significant. The overall reduction in codes has been from 568 FAA codes to 488 JASC codes, with the significant increase being in the structural area as stated earlier.

The JASC code divides the engine section into two major code groups to separate the turbine and reciprocating engines. The codes for the turbine engines are in JASC Chapter 72, Turbine/Turboprop Engine. The codes for the reciprocating engines are now exclusively found in JASC Chapter 85, Reciprocating Engine.

The other major deviation from ATA Spec 100 is in ATA section 2730, specifically involves the stall warning system. Early technology (primarily on smaller aircraft) directly linked the sensing of flight attitude to one of the components which furnished the means of manually controlling the flight attitude characteristics (elevator). Today, most large transport category aircraft utilize electronic units to sense the change in the environmental condition called stall, and use the data to influence navigation. ATA section 3410, Flight Environment Data, includes high speed warning in its code definition. Stall warning (low speed) is the reciprocal term of high speed warning, so its filing under the same code appears more logical. Thus, with the JASC code it was decided to move the stall warning system to Chapter 34 under the separate code JASC code 3418, Stall Warning System.

The FAA is continuing to pursue worldwide involvement from operators and manufacturers in addressing the need for international standardization of aircraft system/component codes. The ultimate goal is to develop a universal aircraft/component numbering standard which can be used in the manufacturer's maintenance manual, wiring diagram manual, system manuals and illustrated parts catalog. This harmonized standard must be a usable standard for the aircraft manufacturers, air carrier operators and the general aviation community.

We welcome comments and feedback regarding the possible forming of working groups to achieve this long range consideration of possibly harmonizing the ATA Specification 100 code and the JASC code. Comments may be directed to the FAA, Aviation Data Sytem Branch, AFS-620, P.O. Box 25082, Oklahoma City, OK 73125.

# JOINT AIRCRAFT SYSTEM/COMPONENT CODE TABLE

## JASC/ TITLE

### 11 PLACARDS AND MARKINGS

1100 PLACARDS AND MARKINGS

### 12 SERVICING

1210 FUEL SERVICING  
1220 OIL SERVICING  
1230 HYDRAULIC FLUID SERVICING  
1240 COOLANT SERVICING

### 18 HELICOPTER VIBRATION

1800 HELICOPTER VIB/NOISE ANALYSIS  
1810 HELICOPTER VIBRATION ANALYSIS  
1820 HELICOPTER NOISE ANALYSIS

### 21 AIR CONDITIONING

2100 AIR CONDITIONING SYSTEM  
2110 CABIN COMPRESSOR SYSTEM  
2120 AIR DISTRIBUTION SYSTEM  
2121 AIR DISTRIBUTION FAN  
2130 CABIN PRESSURE CONTROL SYSTEM  
2131 CABIN PRESSURE CONTROLLER  
2132 CABIN PRESSURE INDICATOR  
2133 PRESSURE REGUL/OUTFLOW VALVE  
2134 CABIN PRESSURE SENSOR  
2140 HEATING SYSTEM  
2150 CABIN COOLING SYSTEM  
2160 CABIN TEMPERATURE CONTROL SYSTEM  
2161 CABIN TEMPERATURE CONTROLLER  
2162 CABIN TEMPERATURE INDICATOR  
2163 CABIN TEMPERATURE SENSOR  
2170 HUMIDITY CONTROL SYSTEM

### 22 AUTO FLIGHT

2200 AUTO FLIGHT SYSTEM  
2210 AUTOPILOT SYSTEM  
2211 AUTOPILOT COMPUTER  
2212 ALTITUDE CONTROLLER  
2213 FLIGHT CONTROLLER  
2214 AUTOPILOT TRIM INDICATOR  
2215 AUTOPILOT MAIN SERVO  
2216 AUTOPILOT TRIM SERVO  
2220 SPEED-ATTITUDE CORRECT. SYSTEM  
2230 AUTO THROTTLE SYSTEM  
2250 AERODYNAMIC LOAD ALLEVIATING

### 23 COMMUNICATIONS

2300 COMMUNICATIONS SYSTEM  
2310 HF COMMUNICATION SYSTEM  
2311 UHF COMMUNICATION SYSTEM  
2312 VHF COMMUNICATION SYSTEM  
2320 DATA TRANSMISSION AUTO CALL  
2330 ENTERTAINMENT SYSTEM  
2340 INTERPHONE & PA SYSTEM  
2350 AUDIO INTEGRATING SYSTEM  
2360 STATIC DISCHARGE SYSTEM  
2370 AUDIO/VIDEO MONITORING

### 24 ELECTRICAL POWER

2400 ELECTRICAL POWER SYSTEM  
2410 ALTERNATOR-GENERATOR DRIVE  
2420 AC GENERATION SYSTEM  
2421 AC GENERATOR-ALTERNATOR  
2422 AC INVERTER  
2423 PHASE ADAPTER

### 24 ELECTRICAL POWER CONT'D

2424 AC REGULATOR  
2425 AC INDICATING SYSTEM  
2430 DC GENERATING SYSTEM  
2431 BATTERY OVERHEAT WARN. SYSTEM  
2432 BATTERY/CHARGER SYSTEM  
2433 DC RECTIFIER-CONVERTER  
2434 DC GENERATOR-ALTERNATOR  
2435 STARTER-GENERATOR  
2436 DC REGULATOR  
2437 DC INDICATING SYSTEM  
2440 EXTERNAL POWER SYSTEM  
2450 AC POWER DISTRIBUTION SYSTEM  
2460 DC POWER/DISTRIBUTION SYSTEM

### 25 EQUIPMENT/FURNISHINGS

2500 CABIN EQUIPMENT/FURNISHINGS  
2510 FLIGHT COMPARTMENT EQUIPMENT  
2520 PASSENGER COMPARTMENT EQUIPMENT  
2530 BUFFET/GALLEYS  
2540 LAVATORIES  
2550 CARGO COMPARTMENTS  
2551 AGRICULTURAL SPRAY SYSTEM  
2560 EMERGENCY EQUIPMENT  
2561 LIFE JACKET  
2562 EMERGENCY LOCATOR BEACON  
2563 PARACHUTE  
2564 LIFE RAFT  
2565 ESCAPE SLIDE  
2570 ACCESSORY COMPARTMENT  
2571 BATTERY BOX STRUCTURE  
2572 ELECTRONIC SHELF SECTION

**26 FIRE PROTECTION**

2600 FIRE PROTECTION SYSTEM  
2610 DETECTION SYSTEM  
2611 SMOKE DETECTION  
2612 FIRE DETECTION  
2613 OVERHEAT DETECTION  
2620 EXTINGUISHING SYSTEM  
2621 FIRE BOTTLE, FIXED  
2622 FIRE BOTTLE, PORTABLE

**27 FLIGHT CONTROLS**

2700 FLIGHT CONTROL SYSTEM  
2701 CONTROL COLUMN SECTION  
2710 AILERON CONTROL SYSTEM  
2711 AILERON TAB CONTROL SYSTEM  
2720 RUDDER CONTROL SYSTEM  
2721 RUDDER TAB CONTROL SYSTEM  
2722 RUDDER ACTUATOR  
2730 ELEVATOR CONTROL SYSTEM  
2731 ELEVATOR TAB CONTROL SYSTEM  
2740 STABILIZER CONTROL SYSTEM  
2741 STABILIZER POSITION INDICATING  
2742 STABILIZER ACTUATOR  
2750 TE FLAP CONTROL SYSTEM  
2751 TE FLAP POSITION IND. SYSTEM  
2752 TE FLAP ACTUATOR  
2760 DRAG CONTROL SYSTEM  
2761 DRAG CONTROL ACTUATOR  
2770 GUST LOCK/DAMPER SYSTEM  
2780 LE FLAP CONTROL SYSTEM  
2781 LE FLAP POSITION IND. SYSTEM  
2782 LE FLAP ACTUATOR

**28 FUEL**

2800 AIRCRAFT FUEL SYSTEM  
2810 FUEL STORAGE  
2820 ACFT FUEL DISTRIB. SYSTEM  
2821 ACFT FUEL FILTER/STRAINER  
2822 FUEL BOOST PUMP  
2823 FUEL SELECTOR/SHUTOFF VALVE  
2824 FUEL TRANSFER VALVE  
2830 FUEL DUMP SYSTEM  
2840 ACFT FUEL INDICATING  
2841 FUEL QUANTITY INDICATOR  
2842 FUEL QUANTITY SENSOR  
2843 FUEL TEMPERATURE INDICATING  
2844 FUEL PRESSURE INDICATOR

**29 HYDRAULIC POWER**

2900 HYDRAULIC POWER SYSTEM  
2910 HYDRAULIC, MAIN SYSTEM  
2911 HYDRAULIC POWER-ACCUMULATOR-MAIN  
2912 HYDRAULIC FILTER-MAIN SYSTEM  
2913 HYDRAULIC PUMP. ELECT-ENG.-MAIN  
2914 HYDRAULIC HANDPUMP-MAIN  
2915 HYDRAULIC PRESSURE RELIEF VLV-MAIN  
2916 HYDRAULIC RESERVOIR-MAIN  
2917 HYDRAULIC PRESSURE REGULATOR-MAIN  
2920 HYDRAULIC, AUXILIARY SYSTEM  
2921 HYDRAULIC ACCUMULATOR-AUXILIARY  
2922 HYDRAULIC FILTER-AUXILIARY  
2923 HYDRAULIC PUMP-AUXILIARY  
2925 HYDRAULIC PRESSURE RELIEF-AUXILIARY  
2926 HYDRAULIC RESERVOIR-AUXILIARY  
2927 HYDRAULIC PRESSURE REGULATOR-AUX.  
2930 HYDRAULIC SYSTEM INDICATING  
2931 HYDRAULIC PRESSURE INDICATOR  
2932 HYDRAULIC PRESSURE SENSOR  
2933 HYDRAULIC QUANTITY INDICATOR  
2934 HYDRAULIC QUANTITY SENSOR

**30 ICE AND RAIN PROTECTION**

3000 ICE/RAIN PROTECTION SYSTEM  
3010 AIRFOIL ANTI/DE-ICE SYSTEM  
3020 AIR INTAKE ANTI/DE-ICE SYSTEM  
3030 PITOT/STATIC ANTI-ICE SYSTEM  
3040 WINDSHIELD/DOOR RAIN/ICE REMOVAL  
3050 ANTENNA/RADOME ANTI-ICE/DE-ICE SYSTEM  
3060 PROP/ROTOR ANTI-ICE/DE-ICE SYSTEM  
3070 WATER LINE ANTI-ICE SYSTEM  
3080 ICE DETECTION

**31 INSTRUMENTS**

3100 INDICATING/RECORDING SYSTEM  
3110 INSTRUMENT PANEL  
3120 INDEPENDENT INSTRUMENTS (CLOCK, ETC.)  
3130 DATA RECORDERS (FLT/MAINT)  
3140 CENTRAL COMPUTERS (EICAS)  
3150 CENTRAL WARNING  
3160 CENTRAL DISPLAY  
3170 AUTOMATIC DATA

**32 LANDING GEAR**

3200 LANDING GEAR SYSTEM  
3201 LANDING GEAR/WHEEL FAIRING  
3210 MAIN LANDING GEAR  
3211 MAIN LANDING GEAR ATTACH SECTION  
3212 EMERGENCY FLOTATION SECTION  
3213 MAIN LANDING GEAR STRUT/AXLE/TRUCK  
3220 NOSE/TAIL LANDING GEAR  
3221 NOSE/TAIL LANDING GEAR ATTACH SECTION  
3222 NOSE/TAIL LANDING GEAR STRUT/AXLE  
3230 LANDING GEAR RETRACT/EXT. SYSTEM  
3231 LANDING GEAR DOOR RETRACT SECTION  
3232 LANDING GEAR DOOR ACTUATOR  
3233 LANDING GEAR ACTUATOR  
3234 LANDING GEAR SELECTOR  
3240 LANDING GEAR BRAKE SYSTEM  
3241 BRAKE ANTI-SKID SECTION  
3242 BRAKE  
3243 MASTER CYL/BRAKE VALVE  
3244 TIRE  
3245 TIRE TUBE  
3246 WHEEL/SKI/FLOAT  
3250 LANDING GEAR STEERING SYSTEM  
3251 STEERING UNIT  
3252 SHIMMY DAMPER  
3260 LANDING GEAR POSITION & WARNING  
3270 AUXILIARY GEAR (TAIL SKID)

**33 LIGHTS**

3300 LIGHTING SYSTEM  
3310 FLIGHT COMPARTMENT LIGHTING  
3320 PASSENGER COMPARTMENT LIGHTING  
3330 CARGO COMPARTMENT LIGHTING  
3340 EXTERIOR LIGHTING  
3350 EMERGENCY LIGHTING

**34 NAVIGATION**

3400 NAVIGATION SYSTEM  
3410 FLIGHT ENVIRONMENT DATA  
3411 PITOT/STATIC SYSTEM  
3412 OUTSIDE AIR TEMP. IND./SENSOR  
3413 RATE OF CLIMB INDICATOR  
3414 AIRSPEED/MACH INDICATING  
3415 HIGH SPEED WARNING  
3416 ALTIMETER, BAROMETRIC/ENCODER

### **34 NAVIGATION CONT'D**

3417 AIR DATA COMPUTER  
3418 STALL WARNING SYSTEM  
3420 ATTITUDE AND DIRECTION DATA SYSTEM  
3421 ATTITUDE GYRO & IND. SYSTEM  
3422 DIRECTIONAL GYRO & IND. SYSTEM  
3423 MAGNETIC COMPASS  
3424 TURN & BANK/RATE OF TURN INDICATOR  
3425 INTEGRATED FLT. DIRECTOR SYSTEM  
3430 LANDING & TAXI AIDS  
3431 LOCALIZER/VOR SYSTEM  
3432 GLIDE SLOPE SYSTEM  
3433 MICROWAVE LANDING SYSTEM  
3434 MARKER BEACON SYSTEM  
3435 HEADS UP DISPLAY SYSTEM  
3436 WIND SHEAR DETECTION SYSTEM  
3440 INDEPENDENT POS. DETERMINING SYSTEM  
3441 INERTIAL GUIDANCE SYSTEM  
3442 WEATHER RADAR SYSTEM  
3443 DOPPLER SYSTEM  
3444 GROUND PROXIMITY SYSTEM  
3445 AIR COLLISION AVOIDANCE SYSTEM (TCAS)  
3446 NON RADAR WEATHER SYSTEM  
3450 DEPENDENT POSITION DETERMINING SYSTEM  
3451 DME/TACAN SYSTEM  
3452 ATC TRANSPONDER SYSTEM  
3453 LORAN SYSTEM  
3454 VOR SYSTEM  
3455 ADF SYSTEM  
3456 OMEGA NAVIGATION SYSTEM  
3457 GLOBAL POSITIONING SYSTEM  
3460 FLIGHT MANAGE. COMPUTING SYSTEM

### **35 OXYGEN**

3500 OXYGEN SYSTEM  
3510 CREW OXYGEN SYSTEM  
3520 PASSENGER OXYGEN SYSTEM  
3530 PORTABLE OXYGEN SYSTEM

### **36 PNEUMATIC**

3600 PNEUMATIC SYSTEM  
3610 PNEUMATIC DISTRIBUTION SYSTEM  
3620 PNEUMATIC INDICATING SYSTEM

### **37 VACUUM**

3700 VACUUM SYSTEM  
3710 VACUUM DISTRIBUTION SYSTEM  
3720 VACUUM INDICATING SYSTEM

### **38 WATER/WASTE**

3800 WATER & WASTE SYSTEM  
3810 POTABLE WATER SYSTEM  
3820 WASH WATER SYSTEM  
3830 WASTE DISPOSAL SYSTEM  
3840 AIR SUPPLY (WATER PRESS. SYSTEM)

### **45 CENTRAL MAINT. SYSTEM**

4500 CENTRAL MAINT. COMPUTER

### **49 AIRBORNE AUXILIARY POWER**

4900 AIRBORNE APU SYSTEM  
4910 APU COWLING/CONTAINMENT  
4920 APU CORE ENGINE  
4930 APU ENGINE FUEL & CONTROL  
4940 APU START/IGNITION SYSTEM  
4950 APU BLEED AIR SYSTEM  
4960 APU CONTROLS  
4970 APU INDICATING SYSTEM  
4980 APU EXHAUST SYSTEM  
4990 APU OIL SYSTEM

### **51 STANDARD PRACTICES/STRUCTURES**

5100 STANDARD PRACTICES/STRUCTURES  
5101 AIRCRAFT STRUCTURES  
5102 BALLOON REPORTS

### **52 DOORS**

5200 DOORS  
5210 PASSENGER/CREW DOORS  
5220 EMERGENCY EXIT  
5230 CARGO/BAGGAGE DOORS  
5240 SERVICE DOORS  
5241 GALLEY DOORS  
5242 E/E COMPARTMENT DOORS  
5243 HYDRAULIC COMPARTMENT DOORS  
5244 ACCESSORY COMPARTMENT DOORS  
5245 AIR CONDITIONING COMPART. DOORS  
5246 FLUID SERVICE DOORS

5247 APU DOORS  
5248 TAIL CONE DOORS  
5250 FIXED INNER DOORS  
5260 ENTRANCE STAIRS  
5270 DOOR WARNING SYSTEM  
5280 LANDING GEAR DOORS

### **53 FUSELAGE**

5300 FUSELAGE STRUCTURE (GENERAL)  
5301 AERIAL TOW EQUIPMENT  
5302 ROTORCRAFT TAIL BOOM  
5310 FUSELAGE MAIN STRUCTURE  
5311 FUSELAGE MAIN FRAME  
5312 FUSELAGE MAIN BULKHEAD  
5313 FUSELAGE MAIN LONGERON/STRINGER  
5314 FUSELAGE MAIN KEEL  
5315 FUSELAGE MAIN FLOOR BEAM  
5320 FUSELAGE MISCELLANEOUS STRUCTURE  
5321 FUSELAGE FLOOR PANEL  
5322 FUSELAGE INTERNAL MOUNT STRUCTURE  
5323 FUSELAGE INTERNAL STAIRS  
5324 FUSELAGE FIXED PARTITIONS  
5330 FUSELAGE MAIN PLATE/SKIN  
5340 FUSELAGE MAIN ATTACH FITTINGS  
5341 WING ATTACH FITTINGS (ON FUSELAGE)  
5342 STABILIZER ATTACH FITTINGS  
5343 LANDING GEAR ATTACH FITTINGS  
5344 FUSELAGE DOOR HINGES  
5345 FUSELAGE EQUIPMENT ATTACH FITTINGS  
5346 POWERPLANT ATTACH FITTINGS  
5347 SEAT/CARGO ATTACH FITTINGS  
5350 FUSELAGE AERODYNAMIC FAIRINGS

### **54 NACELLES/PYLONS**

5400 NACELLE/PYLON STRUCTURE  
5410 MAIN FRAME (ON NACELLE/PYLON)  
5411 FRAME/SPAR/RIB(NACELLE/PYLON)  
5412 BULKHEAD/FIREWALL (NAC/PYLON)  
5413 LONGERON/STRINGER (NAC/PYLON)  
5414 PLATE SKIN (NAC/PYLONS)  
5415 ATTACH FITTINGS (NAC/PYLON)

### **55 STABILIZERS**

5500 EMPENNAGE STRUCTURE  
5510 HORIZONTAL STABILIZER STRUCTURE  
5511 HORIZONTAL STABILIZER SPAR/RIB  
5512 HORIZONTAL STABILIZER PLATE/SKIN  
5513 HORIZONTAL STABILIZER TAB STRUCTURE  
5520 ELEVATOR STRUCTURE

**55 STABILIZERS CONT'D**

5521 ELEVATOR SPAR/RIB STRUCTURE  
5522 ELEVATOR PLATES/SKIN STRUCTURE  
5523 ELEVATOR TAB STRUCTURE  
5530 VERTICAL STABILIZER STRUCTURE  
5531 VERTICAL STABILIZER SPAR/RIB STRUCTURE  
5532 VERTICAL STABILIZER PLATES/SKIN  
5533 VENTRAL STRUCTURE (ON VERT. STAB)  
5540 RUDDER STRUCTURE  
5541 RUDDER SPAR/RIB STRUCTURE  
5542 RUDDER PLATE/SKIN STRUCTURE  
5543 RUDDER TAB STRUCTURE  
5550 EMPENNAGE FLT. CONT. ATTACH FITTING  
5551 HORIZONTAL STABILIZER ATTACH FITTING  
5552 ELEVATOR/TAB ATTACH FITTINGS  
5553 VERT. STAB. ATTACH FITTINGS  
5554 RUDDER/TAB ATTACH FITTINGS

**56 WINDOWS**

5600 WINDOW/WINDSHIELD SYSTEM  
5610 FLIGHT COMPARTMENT WINDOWS  
5620 PASSENGER COMPARTMENT WINDOWS  
5630 DOOR WINDOWS  
5640 INSPECTION WINDOWS

**57 WINGS**

5700 WING STRUCTURE  
5710 WING MAIN FRAME STRUCTURE  
5711 WING SPAR STRUCTURE  
5712 WING RIB STRUCTURE  
5713 WING LONGERON/STRINGER  
5714 WING CENTER BOX  
5720 WING MISCELLANEOUS STRUCTURE  
5730 WING PLATES/SKINS  
5740 WING ATTACH FITTINGS  
5741 WING, FUSELAGE ATTACH FITTINGS  
5742 WING, NAC/PYLON ATTACH FITTINGS  
5743 WING, LANDING GEAR ATTACH FITTINGS  
5744 CONTROL SURFACE ATTACH FITTINGS  
5750 WING CONTROL SURFACE STRUCTURE  
5751 AILERON STRUCTURE  
5752 AILERON TAB STRUCTURE  
5753 TE FLAP STRUCTURE  
5754 LEADING EDGE DEVICE STRUCTURE  
5755 SPOILER STRUCTURE

**61 PROPELLERS/PROPULSORS**

6100 PROPELLER SYSTEM  
6110 PROPELLER ASSEMBLY  
6111 PROPELLER BLADE SECTION  
6112 PROPELLER DE-ICE BOOT SECTION  
6113 PROPELLER SPINNER SECTION  
6114 PROPELLER HUB SECTION  
6120 PROPELLER CONTROL SYSTEM  
6121 PROPELLER SYNCHRONIZER SECTION  
6122 PROPELLER GOVERNOR  
6123 PROPELLER FEATHERING/REVERSING  
6130 PROPELLER BRAKING  
6140 PROPELLER INDICATING SYSTEM

**62 MAIN ROTOR**

6200 MAIN ROTOR SYSTEM  
6210 MAIN ROTOR BLADES  
6220 MAIN ROTOR HEAD  
6230 MAIN ROTOR MAST/SWASHPLATE  
6240 MAIN ROTOR INDICATING SYSTEM

**63 MAIN ROTOR DRIVE**

6300 MAIN ROTOR DRIVE SYSTEM  
6310 ENGINE/TRANSMISSION COUPLING  
6320 MAIN ROTOR GEARBOX  
6321 MAIN ROTOR BRAKE  
6322 ROTORCRAFT COOLING FAN SYSTEM  
6330 MAIN ROTOR TRANSMISSION MOUNT  
6340 ROTOR DRIVE INDICATING SYSTEM

**64 TAIL ROTOR**

6400 TAIL ROTOR SYSTEM  
6410 TAIL ROTOR BLADE  
6420 TAIL ROTOR HEAD  
6440 TAIL ROTOR INDICATING SYSTEM

**65 TAIL ROTOR DRIVE**

6500 TAIL ROTOR DRIVE SYSTEM  
6510 TAIL ROTOR DRIVE SHAFT  
6520 TAIL ROTOR GEARBOX  
6540 TAIL ROTOR DRIVE INDICATING SYSTEM

**67 ROTORS FLIGHT CONTROL**

6700 ROTORCRAFT FLIGHT CONTROL  
6710 MAIN ROTOR CONTROL  
6711 TILT ROTOR FLIGHT CONTROL  
6720 TAIL ROTOR CONTROL SYSTEM  
6730 ROTORCRAFT SERVO SYSTEM

**71 POWERPLANT**

7100 POWERPLANT SYSTEM  
7110 ENGINE COWLING SYSTEM  
7111 COWL FLAP SYSTEM  
7112 ENGINE AIR BAFFLE SECTION  
7120 ENGINE MOUNT SECTION  
7130 ENGINE FIRESEALS  
7160 ENGINE AIR INTAKE SYSTEM  
7170 ENGINE DRAINS

**72 TURBINE/TURBOPROP ENGINE**

7200 ENGINE (TURBINE/TURBOPROP)  
7210 TURBINE ENGINE REDUCTION GEAR  
7220 TURBINE ENGINE AIR INLET SECTION  
7230 TURBINE ENGINE COMPRESSOR SECTION  
7240 TURBINE ENGINE COMBUSTION SECTION  
7250 TURBINE SECTION  
7260 TURBINE ENGINE ACCESSORY DRIVE  
7261 TURBINE ENGINE OIL SYSTEM  
7270 TURBINE ENGINE BYPASS SECTION

**73 ENGINE FUEL & CONTROL**

7300 ENGINE FUEL & CONTROL  
7310 ENGINE FUEL DISTRIBUTION  
7311 ENGINE FUEL-OIL COOLER  
7312 FUEL HEATER  
7313 FUEL INJECTOR NOZZLE  
7314 ENGINE FUEL PUMP  
7320 FUEL CONTROLLING SYSTEM  
7321 FUEL CONTROL/ELECTRONIC  
7322 FUEL CONTROL/CARBURETOR  
7323 TURBINE GOVERNOR  
7324 FUEL DIVIDER  
7330 ENGINE FUEL INDICATING SYSTEM  
7331 FUEL FLOW INDICATING  
7332 FUEL PRESSURE INDICATING  
7333 FUEL FLOW SENSOR  
7334 FUEL PRESSURE SENSOR

#### **74 IGNITION**

7400 IGNITION SYSTEM  
7410 IGNITION POWER SUPPLY  
7411 LOW TENSION COIL  
7412 EXCITER  
7413 INDUCTION VIBRATOR  
7414 MAGNETO/DISTRIBUTOR  
7420 IGNITION HARNESS (DISTRIBUTION)  
7421 SPARK PLUG/IGNITER  
7430 IGNITION SWITCHING

#### **75 AIR**

7500 ENGINE BLEED AIR SYSTEM  
7510 ENGINE ANTI-ICING SYSTEM  
7520 ENGINE COOLING SYSTEM  
7530 COMPRESSOR BLEED CONTROL  
7531 COMPRESSOR BLEED GOVERNOR  
7532 COMPRESSOR BLEED VALVE  
7540 BLEED AIR INDICATING SYSTEM

#### **76 ENGINE CONTROLS**

7600 ENGINE CONTROLS  
7601 ENGINE SYNCHRONIZING  
7602 MIXTURE CONTROL  
7603 POWER LEVER  
7620 ENGINE EMERGENCY SHUTDOWN SYSTEM

#### **77 ENGINE INDICATING**

7700 ENGINE INDICATING SYSTEM  
7710 POWER INDICATING SYSTEM  
7711 ENGINE PRESSURE RATIO (EPR)  
7712 ENGINE BMEP/TORQUE INDICATING  
7713 MANIFOLD PRESSURE (MP) INDICATING  
7714 ENGINE RPM INDICATING SYSTEM  
7720 ENGINE TEMP. INDICATING SYSTEM  
7721 CYLINDER HEAD TEMP (CHT) INDICATING  
7722 ENG. EGT/TIT INDICATING SYSTEM  
7730 ENGINE IGNITION ANALYZER SYSTEM  
7731 ENGINE IGNITION ANALYZER  
7732 ENGINE VIBRATION ANALYZER  
7740 ENGINE INTEGRATED INSTRUMENT SYSTEM

#### **78 ENGINE EXHAUST**

7800 ENGINE EXHAUST SYSTEM  
7810 ENGINE COLLECTOR/TAILOPIPE/NOZZLE  
7820 ENGINE NOISE SUPPRESSOR  
7830 THRUST REVERSER

#### **79 ENGINE OIL**

7900 ENGINE OIL SYSTEM (AIRFRAME)  
7910 ENGINE OIL STORAGE (AIRFRAME)  
7920 ENGINE OIL DISTRIBUTION (AIRFRAME)  
7921 ENGINE OIL COOLER  
7922 ENGINE OIL TEMP. REGULATOR  
7923 OIL SHUTOFF VALVE  
7930 ENGINE OIL INDICATING SYSTEM  
7931 ENGINE OIL PRESSURE  
7932 ENGINE OIL QUANTITY  
7933 ENGINE OIL TEMPERATURE

#### **80 STARTING**

8000 ENGINE STARTING SYSTEM  
8010 ENGINE CRANKING  
8011 ENGINE STARTER  
8012 ENGINE START VALVES/CONTROLS

#### **81 TURBOCHARGING**

8100 EXHAUST TURBINE SYSTEM (RECIP)  
8110 POWER RECOVERY TURBINE (RECIP)  
8120 EXHAUST TURBOCHARGER

#### **82 WATER INJECTION**

8200 WATER INJECTION SYSTEM

#### **83 ACCESSORY GEARBOXES**

8300 ACCESSORY GEARBOXES

#### **85 RECIPROCATING ENGINE**

8500 ENGINE (RECIPROCATING)  
8510 RECIPROCATING ENGINE FRONT SECTION  
8520 RECIPROCATING ENGINE POWER SECTION

8530 RECIPROCATING ENGINE CYLINDER SECTION  
8540 RECIPROCATING ENGINE REAR SECTION  
8550 RECIPROCATING ENGINE OIL SYSTEM



## ***MECHANICS CREED***

UPON MY HONOR I swear that I shall hold in sacred trust the rights and privileges conferred upon me as a certified mechanic. Knowing full well that the safety and lives of others are dependent upon my skill and judgment, I shall never knowingly subject others to risks which I would not be willing to assume for myself, or for those dear to me.

IN DISCHARGING this trust, I pledge myself never to undertake work or approve work which I feel to be beyond the limits of my knowledge; nor shall I allow any non-certificated superior to persuade me to approve aircraft or equipment as airworthy against my better judgment; nor shall I permit my judgment to be influenced by money or other personal gain; nor shall I pass as airworthy aircraft or equipment about which I am in doubt, either as a result of direct inspection or uncertainty regarding the ability of others who have worked on it to accomplish their work satisfactorily.

I REALIZE the grave responsibility which is mine as a certified airman, to exercise my judgment on the airworthiness of aircraft and equipment. I, therefore, pledge unyielding adherence to these precepts for the advancement of aviation and for the dignity of my vocation.